



Dump scraps on a conveyor



Collect ingot using a mold (milk box)



When a mold is full, detach the ingot.



Remove the ingot from a mold. In doing so, step on the ingot to reduce the volume and give more density to it.



40 lbs

40 lbs



1,500 lbs